



Declaration of Conformity to RoHS Directive

To whom it may concern

We hereby confirm that, to the best of our knowledge, our bearings which are listed in the attached list do not contain the substances restricted by RoHS Directive 2011/65/EU (2015/863, 10 hazardous substances) listed below in excess of the described threshold values:

| No | Restricted Substance Group | Threshold Value |
|----|--|-----------------------|
| 1 | Cadmium (Cd) and its compound | $\leq 100\text{ppm}$ |
| 2 | Hexavalent chromium (Cr 6+) and its compound | $\leq 1000\text{ppm}$ |
| 3 | Lead (Pb) and its compound | $\leq 1000\text{ppm}$ |
| 4 | Mercury (Hg) and its compound | $\leq 1000\text{ppm}$ |
| 5 | Polybrominated biphenyls (PBB) | $\leq 1000\text{ppm}$ |
| 6 | Polybrominated diphenyl ethers (PBDE) | $\leq 1000\text{ppm}$ |
| 7 | Bis(2-ethylhexyl) phthalate (DEHP) | $\leq 1000\text{ppm}$ |
| 8 | Butyl benzyl phthalate (BBP) | $\leq 1000\text{ppm}$ |
| 9 | Dibutyl phthalate (DBP) | $\leq 1000\text{ppm}$ |
| 10 | Diisobutyl phthalate (DIBP) | $\leq 1000\text{ppm}$ |

NOTES: The retainers of F7-15 and F9-17 contain Lead. However, copper alloy containing up to 4% lead by weight is exempted from the directive until 21st July, 2026.

Date: 15th December 2023

Yutaka Sato

Deputy General Manager, Designing Department

Kitanihon Seiki Co., Ltd.

E-mail: info@sppc.co.jp

| EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant |
|--------------|----------------------|-----------|--------------|----------------------|-----------|--------------|----------------------|-----------|
| 30/8 2RS | | SRL | 6804HZZ | | SRL | F63800 2RS | | SRL |
| 30/8ZZ | | SRL | 6804HZZ | | K24 | F63800HZZ | | SRL |
| 3800 2RS | | SRL | 6804ZZ | | SRL | F63800ZZ | | SRL |
| 3800ZZ | | SRL | 6805 | | P13 | F63801ZZ | | SRL |
| 6000 | | P13 | 6805 2RS | | SRL | F6700 2RS | | SRL |
| 6000 2RS | | SRL | 6805 2RU | | SRL | F6700HZZ | | SRL |
| 6000 2RU | | SRL | 6805H | | P13 | F6700ZZ | | SRL |
| 6000H | | P13 | 6805H 2RS | | SRL | F6701ZZ | | SRL |
| 6000H | | AF2 | 6805ZZ | | SRL | F6702ZZ | | SRL |
| 6000H 2RS | | SRL | 6806 | | P13 | F6705 2RS | | SRL |
| 6000H 2RU | SS60002RU | SRL | 6806 2RS | | SRL | F6800 2RS | | SRL |
| 6000HTW 2RS | | SRL | 6806 2RU | | SRL | F6800ZZ | | SRL |
| 6000HZZ | | SRL | 6806H 2RS | | SRL | F6801 2RS | | SRL |
| 6000ZZ | | SRL | 6806ZZ | | SRL | F6801HZZ | | SRL |
| 6001 | | P13 | 6807 | | P13 | F6801ZZ | | SRL |
| 6001 2RS | | SRL | 6807 2RS | | SRL | F6802HZZ | | SRL |
| 6001H | | P13 | 6807 2RU | | SRL | F6802ZZ | | SRL |
| 6001H 2RS | | SRL | 6807H 2RS | | SRL | F6803ZZ | | SRL |
| 6001HZZ | | SRL | 6807HZZ | | SRL | F6804 2RS | | SRL |
| 6001TW | | P13 | 6807ZZ | | SRL | F6804ZZ | | SRL |
| 6001ZZ | | SRL | 6808 | | P13 | F6806 2RS | | SRL |
| 6002 2RS | | SRL | 6808 2RS | | SRL | F6806ZZ | | SRL |
| 6002H | | P13 | 6808H 2RS | | SRL | F681H | SF681 | AF2 |
| 6002H 2RS | | SRL | 6808ZZ | | SRL | F681XH | SF681X | AF2 |
| 6002HZZ | | SRL | 6809 | | P13 | F681XHZZ | | SRL |
| 6003H | | DRY | 6809 2RS | | SRL | F682HZZ | | SRL |
| 6003H 2RS | | SRL | 6809 2RU | | SRL | F682ZZ | | SRL |
| 6003H 2RS-V | 6003H 2VS | SRL | 6809H 2RS | | SRL | F683H | | AF2 |
| 6003HZZ | | SRL | 6809ZZ | | SRL | F683HZZ | | SRL |
| 6004H | | P13 | 6810 | | P13 | F683ZZ | | SRL |
| 6004H 2RS | | SRL | 6810 2RS | | SRL | F684H | | AF2 |
| 6004HZZ | | SRL | 6810H 2RS | | SRL | F684HZZ | | SRL |
| 6005H | | P13 | 6810HZZ | | SRL | F684ZZ | | SRL |
| 6005H 2RS | | SRL | 6810ZZ | | SRL | F685H | | AF2 |
| 6005HZZ | | SRL | 6811 | | P13 | F685H 2RS | | SRL |
| 6006H 2RS | | SRL | 6811 2RS | | SRL | F685HZZ | | SRL |
| 6006HZZ | | SRL | 6811H 2RS | | SRL | F685ZZ | | SRL |
| 6007H 2RS | | SRL | 6811ZZ | | SRL | F686 2RS | | SRL |
| 6007HZZ | | SRL | 6812 | | P13 | F686H | | AF2 |
| 6008H 2RS | | SRL | 6812 2RS | | SRL | F686H 2RS | | SRL |
| 6008HZZ | | SRL | 6812 2RU | | SRL | F686HZZ | | SRL |
| 6009H 2RS | | SRL | 6812ZZ | | SRL | F686ZZ | | SRL |
| 6010H 2RS | | SRL | 6813 2RS | | SRL | F687H | | AF2 |
| 6012H 2RS | | SRL | 6813ZZ | | SRL | F687HZZ | | SRL |
| 601XHZZ | | SRL | 6814 2RS | | SRL | F687ZZ | | SRL |
| 602X | | AF2 | 6814ZZ | | SRL | F688 | | AF2 |
| 602XH | 602HX | AF2 | 6815 | | P13 | F688 2RS | | SRL |
| 602XHZZ | | SRL | 6815 2RS | | SRL | F688H | | AF2 |
| 602XZZ | | SRL | 6815ZZ | | SRL | F688H 2RS | | SRL |
| 602ZZ | | SRL | 6816 2RS | | SRL | F688HZZ | | SRL |
| 603 | | AF2 | 6816ZZ | | AV2 | F688HZZW6 | | SRL |
| 603ZZ | | SRL | 6817 2RS | | SRL | F688HZZW6 | | PS2 |
| 604 | | P13 | 6818 2RS | | SRL | F688ZZ | | SRL |
| 604 | | AF2 | 6818ZZ | | SRL | F689HZZ | | SRL |
| 604 2RS | | SRL | 6819 | | P13 | F689ZZ | | SRL |
| 604H | | AF2 | 681H | | AF2 | F6900 2RS | | SRL |
| 604H 2RS | | SRL | 681XH | | AF2 | F6900H 2RS | | SRL |
| 604HZZ | | SRL | 681XHZZ | S681XZZ | SRL | F6900ZZ | | SRL |
| 604ZZ | | SRL | 681XHZZ | S681XZZ | WL2 | F6901 | | P13 |
| 605 | | P13 | 681XZZ | | SRL | F6901 2RS | | SRL |
| 605 2RS | | SRL | 682 | | AF2 | F6901H 2RS | | SRL |
| 605H | | AF2 | 682H | | AF2 | F6901ZZ | | SRL |
| 605H 2RS | | SRL | 682HZZ | | SRL | F6902 2RS | | SRL |
| 605HZZ | | SRL | 682XH | 682HX | AF2 | F6902ZZ | | SRL |

| EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant |
|--------------|----------------------|-----------|--------------|----------------------|-----------|--------------|----------------------|-----------|
| 605ZZ | | SRL | 682XHZZ | 682HXZZ | SRL | F6903 2RS | | SRL |
| 606 | | P13 | 682XZZ | | SRL | F6904 2RS | | SRL |
| 606 2RS | | SRL | 682ZZ | | SRL | F6905ZZ | | SRL |
| 606 2RU | | SRL | 683 | | AF2 | F6906 2RS | | SRL |
| 606H | | AF2 | 683 2RS | | SRL | F6906 2RS | | AV2 |
| 606H 2RS | S606 2RS | SRL | 683H | | AF2 | F6906ZZ | | SRL |
| 606HZZ | | SRL | 683HZZ | | SRL | F691H | | AF2 |
| 606ZZ | | SRL | 683HZZ | S683ZZ | PD8 | F691XH | SF691X | AF2 |
| 607 | | P13 | 683ZZ | | SRL | F692HZZ | | SRL |
| 607 2RS | | SRL | 684 | | AF2 | F693H | SF693 | AF2 |
| 607H | | AF2 | 684 2RS | | SRL | F693HZZ | SF693ZZ | SRL |
| 607H 2RS | | SRL | 684H | | AF2 | F693ZZ | | SRL |
| 607H 2RU | | AF2 | 684H 2RS | | SRL | F694HZZ | | SRL |
| 607HZZ | | SRL | 684H(ZZ) | S684W4 | AF2 | F694ZZ | | SRL |
| 607ZZ | | SRL | 684HTTS | 684H 2TS | SRL | F695HZZ | SF695ZZ | SRL |
| 608 | | P13 | 684HZZ | | SRL | F695ZZ | | SRL |
| 608 2RS | | SRL | 684HZZ | S684ZZ | L55 | F696H | | AF2 |
| 608 2RSW11 | | SRL | 684HZZW3.5 | | SRL | F696H 2RS | SF696 2RS | SRL |
| 608 2RU | | SRL | 684HZZW3.5 | | AF2 | F696HZZ | | SRL |
| 608H | | AF2 | 684ZZ | | SRL | F696ZZ | | SRL |
| 608H 2RS | | SRL | 684ZZW3.5 | | SRL | F698H 2RS | | SRL |
| 608H 2RS | | RL2 | 685 | | AF2 | F698HZZ | | SRL |
| 608H 2RS-V | | L55 | 685 2RS | | SRL | F698ZZ | | SRL |
| 608HZZ | | SRL | 685H | | AF2 | F699HZZ | | SRL |
| 608TW | | P13 | 685H 2RS | | SRL | F699ZZ | | SRL |
| 608ZZ | | SRL | 685HZZ | | SRL | F7-13M | | AF2 |
| 608ZZW6 | | SRL | 685ZZ | | SRL | F7-15/LCD* | F7-15 | AF2 |
| 609 | | P13 | 686 | | AF2 | F7-17M | | AF2 |
| 609 2RS | | SRL | 686 2RS | | SRL | F8-16M | | AF2 |
| 609H 2RS | | SRL | 686H | | AF2 | F8-19M | | AF2 |
| 609HZZ | | SRL | 686H 2RS | | SRL | F9-17/LCD* | F9-17 | AF2 |
| 609ZZ | | SRL | 686HTTS | 686H 2TS | SRL | F9-20M | | AF2 |
| 6200 2RS | | SRL | 686HZZ | | SRL | FR3ZZ | | SRL |
| 6200H | | P13 | 686ZZ | | SRL | FR4ZZ | | SRL |
| 6200H 2RS | | SRL | 686ZZ | | AF2 | FR6ZZ | | SRL |
| 6200HZZ | | SRL | 686ZZW4.5 | | SRL | FR8ZZ | | SRL |
| 6201H | | P13 | 687 | | AF2 | MF104ZZ | | SRL |
| 6201H 2RS | | SRL | 687 2RS | | SRL | MF105ZZ | | SRL |
| 6201HZZ | | SRL | 687H | | AF2 | MF106 | | AF2 |
| 6201HZZ | | AV2 | 687H 2RS | | SRL | MF106ZZ | | SRL |
| 6201ZZ | | SRL | 687HZZ | | SRL | MF115ZZ | | SRL |
| 6202H 2RS | | SRL | 687ZZ | | SRL | MF126 2RS | | SRL |
| 6202HTW | | P13 | 688 | | AF2 | MF126ZZ | | SRL |
| 6202HZZ | | SRL | 688 2RS | | SRL | MF128ZZ | | SRL |
| 6203H | | P13 | 688 2RSW4 | | SRL | MF137ZZ | | SRL |
| 6203H 2RS | | SRL | 688 2RSW6 | | SRL | MF148ZZ | | SRL |
| 6203HZZ | | SRL | 688 2RU | | SRL | MF52ZZ | | SRL |
| 6204H | | P13 | 688(ZZ) | 688W5 | P13 | MF63 | | AF2 |
| 6204H 2RS | | SRL | 688H | S688 | AF2 | MF63ZZ | | SRL |
| 6204HZZ | | SRL | 688H 2RS | | SRL | MF74 | | AF2 |
| 6205H | | P13 | 688H 2RSW6 | | SRL | MF74ZZ | | SRL |
| 6205H 2RS | | SRL | 688H(ZZ) | 688HW5 | AF2 | MF84 | | AF2 |
| 6205HZZ | | SRL | 688HZZ | | SRL | MF84ZZ | | SRL |
| 6206H 2RS | | SRL | 688HZZW4 | 688ZZHW4 | SRL | MF85ZZ | | SRL |
| 6206H 2RS | | RL2 | 688HZZW6 | | SRL | MF95ZZ | | SRL |
| 6206HZZ | SS6206ZZ | SRL | 688W6 | | P13 | MR104 | | AF2 |
| 6207H 2RS | | SRL | 688ZZ | | SRL | MR104 2RS | | SRL |
| 6207HZZ | | SRL | 688ZZ | | AF2 | MR104ZZ | | SRL |
| 6208H 2RS | | SRL | 688ZZW4 | | SRL | MR105 | | AF2 |
| 6208HZZ | | SRL | 688ZZW6 | | SRL | MR105 2RS | | SRL |
| 6209H 2RS | | SRL | 689 | | AF2 | MR105ZZ | | SRL |
| 6210H 2RS | | SRL | 689 2RS | | SRL | MR106 | | AF2 |
| 623 | | P13 | 689H | | AF2 | MR106ZZ | | SRL |
| 623 2RS | | SRL | 689H 2RS | | SRL | MR115 2RS | | SRL |

| EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant |
|--------------|----------------------|-----------|--------------|----------------------|-----------|--------------|----------------------|-----------|
| 623H | | AF2 | 689HZZ | | SRL | MR115ZZ | | SRL |
| 623H 2RS | | SRL | 689HZZW6 | | SRL | MR117 | | AF2 |
| 623HZZ | | SRL | 689ZZ | | SRL | MR117ZZ | | SRL |
| 623HZZ | | PS2 | 689ZZW6 | | SRL | MR126 | | AF2 |
| 623ZZ | | SRL | 6900 | | P13 | MR126 2RS | | SRL |
| 624 | | P13 | 6900 2RS | | SRL | MR126ZZ | | SRL |
| 624 2RS | | SRL | 6900 2RU | | SRL | MR128 | | AF2 |
| 624 2RU | | SRL | 6900H | | P13 | MR128ZZ | | SRL |
| 624H | S624 | AF2 | 6900H 2RS | | SRL | MR137 | | AF2 |
| 624H | | DRY | 6900HZZ | | SRL | MR137ZZ | | SRL |
| 624H 2RS | | SRL | 6900TW | | P13 | MR148 | | AF2 |
| 624HZ | | DRY | 6900ZZ | | SRL | MR148 2RS | | SRL |
| 624HZZ | | SRL | 6900ZZNR | 6900ZZNR | AV2 | MR148ZZ | | SRL |
| 624HZZ | | K24 | 6901 | | P13 | MR148ZZ | | AF2 |
| 624Z | | AF2 | 6901 2RS | | SRL | MR52 | | AF2 |
| 624ZZ | | SRL | 6901H 2RS | | SRL | MR52ZZ | | SRL |
| 624ZZ | | AF2 | 6901HZZ | | SRL | MR63 | | AF2 |
| 625 | | AF2 | 6901ZZ | | SRL | MR63ZZ | | SRL |
| 625 | | P13 | 6902 | | P13 | MR63ZZ | | AF2 |
| 625 2RS | | SRL | 6902 | | AF2 | MR74 | | AF2 |
| 625 2RU | | SRL | 6902 2RS | | SRL | MR74ZZ | | SRL |
| 625H | | AF2 | 6902 2RU | | SRL | MR83 | | AF2 |
| 625H 2RS | | SRL | 6902H 2RS | | SRL | MR83ZZ | | SRL |
| 625HTW | | AF2 | 6902HZZ | | SRL | MR84 | | AF2 |
| 625HZZ | | SRL | 6902HZZ | | AG2 | MR84ZZ | | SRL |
| 625TW | | P13 | 6902ZZ | | SRL | MR85 | | AF2 |
| 625ZZ | | SRL | 6902ZZNR | | SRL | MR85ZZ | | SRL |
| 625ZZ | | AV2 | 6903 | | P13 | MR85ZZ | | AF2 |
| 625ZZ | | L8A | 6903 2RS | | SRL | MR93ZZ | | SRL |
| 626 | | P13 | 6903 2RU | | SRL | MR95 | | AF2 |
| 626 | | AF2 | 6903H 2RS | | SRL | MR95ZZ | | SRL |
| 626 2RS | | SRL | 6903HZZ | | SRL | MT2015 | ET2015 | P13 |
| 626 2RSW5.15 | | SRL | 6903ZZ | | SRL | MT2520 | ET2520 | P13 |
| 626 2RU | | SRL | 6904 | | P13 | MT2520ZZ | ET2520ZZ | SRL |
| 626H | | AF2 | 6904 2RS | | SRL | R10 | | P13 |
| 626H 2RS | | SRL | 6904H | | P13 | R10 2RS | | SRL |
| 626HZZ | | SRL | 6904H 2RS | | SRL | R10ZZ | | SRL |
| 626HZZ | | L55 | 6904HZZ | | SRL | R12 | | P13 |
| 626ZZ | | SRL | 6904ZZ | | SRL | R12 2RS | | SRL |
| 627 | | P13 | 6905 | | P13 | R12ZZ | | SRL |
| 627 2RS | | SRL | 6905 2RS | | SRL | R144ZZ | | SRL |
| 627H | | P13 | 6905 2RU | | SRL | R155ZZ | | SRL |
| 627H 2RS | | SRL | 6905H 2RS | | SRL | R166 | | P13 |
| 627HZZ | | SRL | 6905ZZ | | SRL | R166ZZ | | SRL |
| 627ZZ | | SRL | 6906 | | P13 | R188 | | AF2 |
| 628 | | P13 | 6906 2RS | | SRL | R188ZZ | | SRL |
| 628 2RS | | SRL | 6906 2RU | | SRL | R2 2RS | | SRL |
| 628H 2RS | | SRL | 6906H 2RS | | SRL | R2-5ZZ | | SRL |
| 628HZZ | | SRL | 6906HZZ | | SRL | R2AZZ | | SRL |
| 628ZZ | | SRL | 6906ZZ | | SRL | R2ZZ | | SRL |
| 629 | | P13 | 6907 | | AF2 | R3 | | AF2 |
| 629 2RS | | SRL | 6907 | | P13 | R3 2RS | | SRL |
| 629H 2RS | | SRL | 6907 2RS | | SRL | R3AZZ | | SRL |
| 629HZZ | | SRL | 6907 2RU | | SRL | R3ZZ | | SRL |
| 629ZZ | | SRL | 6907H 2RS | | SRL | R4 | | P13 |
| 6300H 2RS | | SRL | 6907ZZ | | SRL | R4 2RS | | SRL |
| 6300HZZ | | SRL | 6908 | | P13 | R4A | | AF2 |
| 6301H 2RS | | SRL | 6908 2RS | | SRL | R4A | | P13 |
| 6301HZZ | | SRL | 6908 2RU | | SRL | R4A 2RS | | SRL |
| 6302H 2RS | | SRL | 6908H 2RS | | SRL | R4AZZ | | SRL |
| 6303H 2RS | | SRL | 6908HZZ | | SRL | R4ZZ | | SRL |
| 6304H 2RS | | SRL | 6908ZZ | | SRL | R4ZZ | | PS2 |
| 6304HZZ | | SRL | 6909 | | P13 | R6 | | AF2 |
| 6305H 2RS | | SRL | 6909 2RS | | SRL | R6 2RS | | SRL |

| EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant |
|--------------|----------------------|-----------|--------------|----------------------|-----------|--------------|----------------------|-----------|
| 6305HZZ | | SRL | 6909H 2RS | | SRL | R6ZZ | | SRL |
| 6306H 2RS | | SRL | 6909HZZ | | SRL | R8 | | P13 |
| 6307H 2RS | | SRL | 6909ZZ | | SRL | R8 | | AF2 |
| 633HZZ | | SRL | 6910 2RS | | SRL | R8 2RS | | SRL |
| 633ZZ | | SRL | 6910 2RU | | SRL | R8ZZ | | SRL |
| 634 2RS | | SRL | 6910H | | AF2 | SFR1 | | AF2 |
| 634H 2RS | | SRL | 6910ZZ | | SRL | SFR1-5ZZ | | SRL |
| 634HZZ | | SRL | 6911 | | P13 | SFR133ZZ | | SRL |
| 634ZZ | | SRL | 6911 2RS | | SRL | SFR144 | | AF2 |
| 635 2RS | | SRL | 6911ZZ | | SRL | SFR144ZZ | | SRL |
| 635H | | AF2 | 6912 | | P13 | SFR156ZZ | | SRL |
| 635H 2RS | | SRL | 6912 2RS | | SRL | SFR166ZZ | | SRL |
| 635HZZ | | SRL | 6912ZZ | | SRL | SFR168ZZ | FR168HZZ | SRL |
| 635ZZ | | SRL | 6913 2RS | | SRL | SFR1810ZZ | FR1810HZZ | SRL |
| 636H 2RS | | SRL | 6913ZZ | | SRL | SFR188 | | AF2 |
| 636HZZ | | SRL | 6914 2RS | | SRL | SFR188ZZ | | SRL |
| 636ZZ | | SRL | 6914ZZ | | AV2 | SFR2-5 | | AF2 |
| 637ZZ | | SRL | 6915 2RS | | SRL | SFR2-5ZZ | FR2-5HZZ | SRL |
| 638 2RS | | SRL | 6915ZZ | | AV2 | SFR3ZZ | FR3HZZ | SRL |
| 63800 | | P13 | 6916 2RS | | SRL | SFR4ZZ | | SRL |
| 63800 2RS | | SRL | 6916ZZ | | SRL | SFR6ZZ | | SRL |
| 63800H 2RS | SS63800 2RS | SRL | 6918 2RS | | SRL | SFR8ZZ | | SRL |
| 63800HZZ | | SRL | 691H | | AF2 | SFRW168ZZ | | SRL |
| 63800HZZ | | L8A | 691XH | 691HX | AF2 | SMF104 | | AF2 |
| 63800ZZ | | SRL | 691XH(ZZ) | S691XW2.6 | AF2 | SMF104ZZ | | SRL |
| 63801 2RS | | SRL | 691XHZZ | | SRL | SMF106ZZ | | SRL |
| 63801H 2RS | | SRL | 691XHZZW2 | S691XZZW2 | SRL | SMF115ZZ | MF115HZZ | SRL |
| 63801H 2RS | | AV2 | 692 | | AF2 | SMF117ZZ | | SRL |
| 63801ZZ | | SRL | 692H | | AF2 | SMF126ZZ | MF126HZZ | SRL |
| 63802 2RS | | SRL | 692HZZ | | SRL | SMF128ZZ | | SRL |
| 63802H 2RS | | SRL | 692HZZW2.3 | | SRL | SMF137ZZ | | SRL |
| 63802ZZ | | SRL | 692XH | 692HX | AF2 | SMF148 | | AF2 |
| 63803 2RS | | SRL | 692XHZZ | 692HXZZ | SRL | SMF148ZZ | | SRL |
| 63803ZZ | | SRL | 692XZZ | | SRL | SMF52ZZ | MF52HZZ | SRL |
| 63804ZZ | | SRL | 692ZZ | | SRL | SMF62 | | AF2 |
| 638HZZ | | SRL | 693 | | AF2 | SMF63ZZ | | SRL |
| 638ZZ | | SRL | 693 2RS | | SRL | SMF74ZZ | MF74HZZ | SRL |
| 639ZZ | | SRL | 693H | | AF2 | SMF83 | | AF2 |
| 6700 | | AF2 | 693HZZ | 693HZZ | SRL | SMF84ZZ | | SRL |
| 6700 2RS | | SRL | 693ZZ | | SRL | SMF85ZZ | | SRL |
| 6700H | | AF2 | 694 | | P13 | SMF95ZZ | | SRL |
| 6700H 2RS | | SRL | 694 2RS | | SRL | SMR104 | MR104H | AF2 |
| 6700HZZ | | SRL | 694H | | AF2 | SMR104 2RS | | SRL |
| 6700ZZ | | SRL | 694H 2RS | | SRL | SMR104ZZ | | SRL |
| 6701 | | P13 | 694HZZ | | SRL | SMR105 | | AF2 |
| 6701 2RS | | SRL | 694HZZ | | AF2 | SMR105ZZ | | SRL |
| 6701HZZ | | SRL | 694HZZ | S694ZZ | DRY | SMR106 | MRH106 | AF2 |
| 6701ZZ | | SRL | 694ZZ | | SRL | SMR106ZZ | | SRL |
| 6702 2RS | | SRL | 695 | | P13 | SMR115ZZ | MR115HZZ | SRL |
| 6702H 2RS | | SRL | 695 2RS | | SRL | SMR117 | | AF2 |
| 6702HZZ | SS6702ZZ | SRL | 695 2RSW5 | | SRL | SMR117ZZ | | SRL |
| 6702ZZ | | SRL | 695H | | AF2 | SMR126 | | AF2 |
| 6703 2RS | | SRL | 695H 2RS | | SRL | SMR126ZZ | | SRL |
| 6703Z | 6703RS/Z | DRY | 695HZZ | | SRL | SMR128 | MR128H | AF2 |
| 6703ZZ | | SRL | 695W5 | | P13 | SMR128ZZ | MR128HZZ | SRL |
| 6704 | | P13 | 695ZZ | | SRL | SMR137 | | AF2 |
| 6704 2RS | | SRL | 695ZZW5 | | SRL | SMR137ZZ | MR137HZZ | SRL |
| 6704H 2RS | | SRL | 696 | | P13 | SMR148 | | AF2 |
| 6704HZZ | | SRL | 696 2RS | | SRL | SMR148 2RS | MR148H 2RS | SRL |
| 6704ZZ | | SRL | 696A 2RS | | SRL | SMR148ZZ | MR148HZZ | SRL |
| 6705 | | P13 | 696AH 2RS | S696A 2RS | SRL | SMR31 | | AF2 |
| 6705 2RS | | SRL | 696AHZZ | 696HAZZ | SRL | SMR41X | | AF2 |
| 6705 2RU | | SRL | 696AZZ | | SRL | SMR52 | | AF2 |
| 6705H | | P13 | 696H 2RS | | SRL | SMR52ZZ | MR52HZZ | SRL |

| EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant | EZO Part No. | Alternative Part No. | Lubricant |
|--------------|----------------------|-----------|--------------|----------------------|-----------|--------------|----------------------|-----------|
| 6705H 2RS | | SRL | 696HZZ | | SRL | SMR62ZZ | MR62HZZ | SRL |
| 6705HZZ | | SRL | 696ZZ | | SRL | SMR63 | | AF2 |
| 6705ZZ | | SRL | 697 | | P13 | SMR63 | | L8A |
| 6706 | | P13 | 697 2RS | | SRL | SMR63ZZ | MR63HZZ | SRL |
| 6706HVV | 6706H 2RU | SRL | 697H 2RS | | SRL | SMR63ZZW3 | | SRL |
| 6706VV | 6706 2RU | SRL | 697HZZ | | SRL | SMR72 | | AF2 |
| 6706ZZ | | SRL | 697ZZ | | SRL | SMR72ZZ | | SRL |
| 6707 2RS | | SRL | 698 | | P13 | SMR74 | | AF2 |
| 6707H 2RS | | SRL | 698 2RS | | SRL | SMR74ZZ | | SRL |
| 6708 2RS | | SRL | 698H | | AF2 | SMR83 | MR83H | AF2 |
| 6709 2RS | | SRL | 698H 2RS | | SRL | SMR83ZZ | | SRL |
| 6710 | | P13 | 698HZZ | | SRL | SMR84 | | AF2 |
| 6710 2RS | | SRL | 698ZZ | | SRL | SMR84ZZ | | SRL |
| 672H | | AF2 | 699 | | P13 | SMR85 | MR85H | AF2 |
| 672HZZ | | SRL | 699 2RS | | SRL | SMR85ZZ | | SRL |
| 679HW3 | 679H | AF2 | 699H | | AF2 | SMR85ZZW3 | | SRL |
| 679HZZ | | SRL | 699H 2RS | | SRL | SMR93 | | AF2 |
| 679W3 | 679 | AF2 | 699HZZ | | SRL | SMR93ZZ | MR93HZZ | SRL |
| 679ZZ | | SRL | 699ZZ | | SRL | SMR95 | MR95H | AF2 |
| 68/0.6H | S68/0.6 | AF2 | F10-18M | | AF2 | SMR95ZZ | | SRL |
| 6800 | | P13 | F2-6/LCD | F2-6 | AF2 | SR1-5ZZ | | SRL |
| 6800 2RS | | SRL | F3-8M | | AF2 | SR133 | | AF2 |
| 6800 2RU | | SRL | F4-10M | | AF2 | SR133ZZ | | SRL |
| 6800H | | AF2 | F4-9M | | AF2 | SR144 | R144H | AF2 |
| 6800H 2RS | | SRL | F5-12M | | AF2 | SR144ZZ | | SRL |
| 6800H 2RU | SS68002RU | SRL | F6-12M | | AF2 | SR156ZZ | R156HZZ | SRL |
| 6800HZZ | | SRL | F6-14M | | AF2 | SR166ZZ | | SRL |
| 6800TW | | P13 | F601XHZZ | SF601XZZ | SRL | SR168ZZ | | SRL |
| 6800ZZ | | SRL | F602HZZ | SF602ZZ | SRL | SR1810ZZ | | SRL |
| 6801 | | P13 | F604ZZ | | SRL | SR188 | R188H | AF2 |
| 6801 2RS | | SRL | F605HZZ | SF605ZZ | SRL | SR188TTS | SR188 2TS | SRL |
| 6801H | | P13 | F605ZZ | | SRL | SR188ZZ | R188HZZ | SRL |
| 6801H 2RS | | SRL | F606H 2RS | SF606 2RS | SRL | SR2-5 | R2-5H | AF2 |
| 6801HZZ | | SRL | F606HZZ | SF606ZZ | SRL | SR2-5ZZ | | SRL |
| 6801ZZ | | SRL | F606ZZ | | SRL | SR2-6 | R2-6H | AF2 |
| 6802 | | P13 | F607 2RS | | SRL | SR2-6ZZ | | SRL |
| 6802 2RS | | SRL | F607H 2RS | | SRL | SR2ZZ | | SRL |
| 6802 2RU | | SRL | F607HZZ | | SRL | SR3ZZ | | SRL |
| 6802H | | AF2 | F607ZZ | | SRL | SR4A 2RS | | SRL |
| 6802H 2RS | | SRL | F608 | | P13 | SR4AZZ | | SRL |
| 6802HZZ | | SRL | F608 2RS | | SRL | SR4ZZ | | SRL |
| 6802ZZ | | SRL | F608H 2RS | | SRL | SR6 | | AF2 |
| 6803 | | P13 | F608HZZ | | SRL | SR6 2RS | R6H 2RS | SRL |
| 6803 2RS | | SRL | F608ZZ | | SRL | SR6ZZ | | SRL |
| 6803 2RU | | SRL | F609ZZ | | SRL | SR8 2RS | | SRL |
| 6803H | | AF2 | F623HZZ | | SRL | SR8ZZ | R8HZZ | SRL |
| 6803H 2RS | | SRL | F623ZZ | | SRL | SSRI-1038ZZ | SR1038ZZ | SRL |
| 6803HZZ | | SRL | F624HZZ | | SRL | SSRI-1212ZZ | SR1212ZZ | SRL |
| 6803ZZ | | SRL | F624ZZ | | SRL | SSRI-1458ZZ | SR1458ZZ | SRL |
| 6804 | | P13 | F625ZZ | | SRL | SSRI-1458ZZS | SER1458ZZS | SRL |
| 6804 | | AF2 | F626 2RS | | SRL | SSRI-1634ZZ | R1634HZZ | SRL |
| 6804 2RS | | SRL | F626ZZ | | SRL | Y17ZZ | | SRL |
| 6804 2RU | | SRL | F627ZZ | | SRL | | | |
| 6804H 2RS | | SRL | F634HZZ | | SRL | | | |

*The retainers of F7-15 and F9-17 contain Lead.

However, copper alloy containing up to 4% lead by weight is exempted from the directive until 21st July, 2026.